


# Back Mounted Power Strips Assembly

Roosevelt & Roosevelt Hydraulic Series

1. Position the power strip either



a. On the top of a shelf or the work surface.

b. Under the shelf or work surface.

2. Insert two screws in each bracket using a power tool.

